i7/i9/Pre-XR Customer Release Notes

Please see Update instructions for installation.

Release 2.5

This release includes the following:

- Unit lockup when DAC filter menu navigated (RM702).

Release 2.4.3

This release includes the following:

- Remove PSU-XR from i7 Menu
- Fix low temperature start-up issue

Release 2.3.00

This release includes the following:

- LED settings can now be adjusted over MCBUS when using a Cyrus XR series integrated or pre amplifier
- Fixed dropouts on optical inputs with some digital sources

Release 2.2.00

This release was never made public.

Release 2.1.00

This release includes the following:

- Fixed Software Version not showing correctly in menu

Release 2.0.12

This release includes the following:

- Support for the Cyrus PSU-XR
- Allows mains errors to be recovered by holding the Standby touch pad for 1 second.
- Updated thermal recovery

Copyright